

EXHIBIT 11







OFF ■ 08-30-2016, 11:13 AM

brianw0048 2014 STX SCREW iTrader: (1)



Join Date: Mar 2014 Location: Barboursville, WV Posts: 709 Thanks: 56 Thanked 106 Times in 67



just came on.

I have 3 or 4 on my '14 that were like that. I took a dremel and cut off the chrome cap.

I thought it was from the dealer using air tools to put the lugs back on, but of course they won't admit that's the issue.

I was thinking the same thing about the air tools. Like you said they are not gonna admit it. An now I'm having another issue. The Tire Pressure Sensor Fault







Join Date: Mar 2014 Posts: 13

Thanks: 4 Thanked 0 Times in 0 Posts





■ 08-30-2016, 11:39 AM

berty Beer, Boats, and Trucks.



https://www.amazon.com/gp/product/B0...?ie=UTF8&psc=1

dont look back. Very common issue with the crappy OEM lugs. Two dissimilar



Join Date: Oct 2015 Location: Baltimore, MD Posts: 3,042 Thanks: 833 Thanked 568 Times in 438



metals, salt from the road, heat, a million other reasons for them to fall apart. Check out my link, they are perfect size lug nut replacements. Solid 1 piece

■ 08-30-2016, 11:43 AM

Jack-Daniel Senior Member



Join Date: Oct 2015 Location: Ontario's Near North Posts: 451 Thanks: 78 Thanked 77 Times in 52



corrosion causing cap to split from my 2011

There are other threads on this problem. corrosion under the 'cap' then the socket won't fit> #1 issue 'tech' not using the proper deep socket, twisting the crap out of the 'cap'

Last edited by Jack-Daniel; 08-30-2016 at 11:46 AM.

OFF







Join Date: Jan 2009 Location: Va. Beach, VA. Posts: 30,489 Thanked 1,390 Times in

Quote:

Originally Posted by Brandon L Thompson D

I have a 2011 f150. Just had my tires rotated and the service tech told me that I have 3 lugs nuts with chrome cover cracking on them. He said that this is caused by the lug nuts getting hot and the chrome swelling. Has anybody else had this problem.

Attachment 446274

That looks like somebody used the improper socket to try and remove it..

■ 08-30-2016, 11:47 AM

berty


Beer, Boats, and Trucks.



Join Date: Oct 2015 Location: Baltimore, MD Posts: 3,042

oh yikes, picture didn't load the first time I read through but yeah like stated above looks like they didn't seat the socket all the way back on the nut





POST REPLY				Page 1 of 2 1 2 > V	
Related Topics					
Thread	Thread Starter	Forum	Replies	Last Post	
2011 3.5 Ecoboost Limp Mode	Jcape	3.5L EB	5	04-24-2016 02:25 PM	
Tire damage question and fx4 rim repair.	greenheadkiller98	1997 - 2003 Ford F150	59	04-12-2016 10:56 PM	
Jack stand placement and tire rotations	gatorblue92	2015 - Present Ford F150	8	04-11-2016 02:56 PM	
2011 f150 5ltr with Glycol leak left side.	napu	2009 - 2014 Ford F150	2	04-07-2016 11:55 PM	


Ó

« Previous Thread | Next Thread »

Wheels & Tires

02-03-2007 10:39 AM

blackwoodfuz



Like 0 Share

lug pattern

G+

Tweet

BB code is On Smilies are On [IMG] code is On HTML code is Off Trackbacks are Off Pingbacks are Off Refbacks are Off

Forum Rules


All times are GMT -4. The time now is $01:25\ \text{PM}.$

Contact Us - Ford F150 Forum - Advertising - Cookie Policy - Privacy Statement - Terms of Service - Top

Copyright © 2006 - 2017 F150 Forum.com
This site is in no way affiliated with the Ford Motor Company.

Our Network: For F150 Forum | F150 Forum | The Mustane Source


Internet Brands* Automotive




2009 - 2014 Ford F150 General discussion on 2009 - 2014 Ford F150 truck.

Sponsored by:





Posts: 3,042



2:17-cv-12794-SJW-INRSuesDPage# 1Eqr2 F1\$Pi Ferting 8/24/74/74y 4PFgr9 Total Fan Pg ID 363



Related Topics					
Thread	Thread Starter	Forum	Replies	Last Post	
2011 3.5 Ecoboost Limp Mode	Jcape	3.5L EB	5	04-24-2016 02:25 PM	
Tire damage question and fx4 rim repair.	greenheadkiller98	1997 - 2003 Ford F150	59	04-12-2016 10:56 PM	
Jack stand placement and tire rotations	gatorblue92	2015 - Present Ford F150	8	04-11-2016 02:56 PM	
2011 f150 5ltr with Glycol leak left side.	napu	2009 - 2014 Ford F150	2	04-07-2016 11:55 PM	
<u>lug pattern</u>	blackwoodfuz	Wheels & Tires	6	02-03-2007 10:39 AM	

« Previous Thread | Next Thread »



All times are GMT -4. The time now is $02:00\ PM$.

